Robert C. Colwell, Reg. No. 27,431

(650) 326-2400


Applicant: Michiobu Mizumura, et al.

Title: Flat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 1 of 9

FIG.1



Robert C. Cohvell, Reg. No. 27,431


(650) 326-2400

Applicant: Michiobu Mizumura, et al. Title: Flat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 2 of 9

FIG.2



12 : Glass pipette13 : Insulating film material13' : Insulating film material coating range

Applicant: Michiobu Mizumura, et al. Title: Flat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 3 of 9

FIG.3






FIG.4




Sheet 4 of 9

FIG.5




Com Com Town of the state of th




Cross section along B-B'

Sheet 5 of 9

FIG.6





Cross section along C-C'


17 : Foreign object18 : Insulating film material

Title: Flat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 6 of 9


FIG.7



19 : Foreign object

Sheet 7 of 9


FIG.8



- 1: Glass substrate
- 2: Scan line
- 3: Signal line
- 4 : Pixel
- 6: TFT structure
- 7 : Shorting defect portion

Sheet 8 of 9

FIG.9



The state of the s

Robert C. Colwell, Reg. No. 27,431

(650) 326-2400


Applicant: Michiobu Mizumura, et al.

Title: Flat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 9 of 9

FIG.10



8: Inter-layer insulating film

9: Laser

10 : Dispersed metal

11, 11': Portion severed by laser